

## Popular Applications

This chart is provided as a reference for your convenience. Every effort has been made to ensure accuracy. However, please note that in rare cases manufacturers do utilize parts with different specs for the same model and discrepancies may occur. Please compare the measurements of your vehicle with RAZO pedals or consult with

a shop employee before making the purchase. Thank you for your support and understanding.

| Competition Sport (bolt-on) |                    |                |                                      | Executive Sport (bolt-on)            |                                   |                                      |                                      | Formula Spec (bolt-on or drill)   |                                      |                                      |                                   |
|-----------------------------|--------------------|----------------|--------------------------------------|--------------------------------------|-----------------------------------|--------------------------------------|--------------------------------------|-----------------------------------|--------------------------------------|--------------------------------------|-----------------------------------|
| Make                        | Model              | Year           | Manual<br>(Accel/Brk&Clutch/FT Rest) | Automatic<br>(Accel/Brake/Foot Rest) | Remark                            | Manual<br>(Accel/Brk&Clutch/FT Rest) | Automatic<br>(Accel/Brake/Foot Rest) | Remark                            | Manual<br>(Accel/Brk&Clutch/FT Rest) | Automatic<br>(Accel/Brake/Foot Rest) | Remark                            |
| Acura                       | CL                 | 1997 - 1999    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Acura                       | Integra            | 1990 - 2001    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   | '90-'93 / '94-'01                 | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   | '90-'93 / '94-'01                 | RP113 / RP115                        | RP111 / RP115                        | '90-'93 / '94-'01                 |
| Acura                       | Legend             | 1986 - 1995    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   | '86-'90 / '91-'95                 | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | '86-'90 / '91-'95                 |                                      |                                      | '86-'90 / '91-'95                 |
| Acura                       | MDX                | 2001 - 2006    |                                      | RP81 / RP83 / RP86                   |                                   |                                      | RP71 / RP73 / RP76                   |                                   |                                      |                                      |                                   |
| Acura                       | NSX                | 1991 - 2005    | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP73 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Acura                       | RDX                | 2007 - present | n/a                                  | RP82 / RP84 / RP86                   |                                   | n/a                                  | RP72 / RP74 / RP76                   |                                   | n/a                                  | RP112 / RP115                        |                                   |
| Acura                       | RL                 | 1996 - 2004    |                                      | RP81 / RP84                          |                                   |                                      | RP71 / RP74                          |                                   |                                      |                                      |                                   |
| Acura                       | RSX                | 2002 - 2006    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Acura                       | SLX                | 1996 - 1999    |                                      | RP81 / RP84 / RP86                   |                                   |                                      | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Acura                       | TL                 | 1996 - 1998    |                                      | RP82 / RP84 / RP86                   |                                   |                                      | RP72 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Acura                       | TL                 | 1999 - 2003    | n/a                                  | RP82 / RP84 / RP86                   |                                   | n/a                                  | RP72 / RP74 / RP76                   |                                   | n/a                                  | RP112 / RP115                        |                                   |
| Acura                       | TL                 | 2004 - 2008    | xxx / RP85 / RP86                    | xxx / RP84 / RP86                    | gas is odd size, no fitment       | xxx / RP75 / RP76                    | xxx / RP74 / RP76                    | gas is odd size, no fitment       | n/a                                  | n/a                                  | gas is odd size, no fitment       |
| Acura                       | TSX                | 2004 - 2008    | xxx / RP85 / RP86                    | xxx / RP84 / RP86                    | gas is odd size, no fitment       | xxx / RP75 / RP76                    | xxx / RP74 / RP76                    | gas is odd size, no fitment       | n/a                                  | n/a                                  | gas is odd size, no fitment       |
| Acura                       | TSX                | 2009 - present | xxx / RP85 / RP86                    | xxx / RP84 / RP86                    | gas is odd size, no fitment       | xxx / RP75 / RP76                    | xxx / RP74 / RP76                    | gas is odd size, no fitment       | n/a                                  | n/a                                  | gas is odd size, no fitment       |
| Acura                       | Vigor              | 1992 - 1994    |                                      | RP82 / RP84 / RP86                   |                                   |                                      | RP72 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Chevrolet                   | Camaro             | 1993 - 2002    | RP82 / RP85                          | RP82 / RP83                          | no space for foot rest            | RP72 / RP75                          | RP72 / RP73                          | no space for foot rest            | RP114                                | RP112                                | no space for foot rest            |
| Chevrolet                   | Camaro             | 2010 - present | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   | extra labor on gas pedal          | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | extra labor on gas pedal          | RP114 / RP115                        | RP112 / RP115                        | extra labor on gas pedal          |
| Chevrolet                   | Cavalier           | 1995 - 2005    | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP73 / RP76                   |                                   | RP114                                | RP112                                |                                   |
| Chevrolet                   | Cobalt             | 2005 - present | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   | Supchrgrd/Turbo clutch no fitment | RP72 / RP75 / RP76                   | RP72 / RP73 / RP76                   | Supchrgrd/Turbo clutch no fitment | RP114 / RP115                        | RP112 / RP115                        | Supchrgrd/Turbo clutch drill only |
| Chevrolet                   | Corvette           | 1997 - present | RP82 / xxx / RP86                    | RP82 / xxx / RP86                    | metal brake&clutch, no fitment    | RP72 / xxx / RP76                    | RP72 / xxx / RP76                    | metal brake&clutch, no fitment    | n/a                                  | n/a                                  | metal brake&clutch, no fitment    |
| Chrysler                    | 300                | 2005 - present | n/a                                  | RP82 / RP84 / RP86                   | SRT model fitment not confirmed   | n/a                                  | RP72 / RP74 / RP76                   | SRT model fitment not confirmed   | n/a                                  | RP112 / RP115                        | SRT model fitment not confirmed   |
| Dodge                       | Charger            | 2006 - present | n/a                                  | RP82 / RP84 / RP86                   | SRT model fitment not confirmed   | n/a                                  | RP72 / RP74 / RP76                   | SRT model fitment not confirmed   | n/a                                  | RP112 / RP115                        | SRT model fitment not confirmed   |
| Dodge                       | Magnum             | 2005 - 2008    | n/a                                  | RP82 / RP84 / RP86                   | SRT model fitment not confirmed   | n/a                                  | RP72 / RP74 / RP76                   | SRT model fitment not confirmed   | n/a                                  | RP112 / RP115                        | SRT model fitment not confirmed   |
| Dodge                       | Neon               | 1995 - 2006    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   | extra labor on SRT-4 gas pedal    | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | extra labor on SRT-4 gas pedal    | RP114 / RP115                        | RP112 / RP115                        | extra labor on SRT-4 gas pedal    |
| Ford                        | Focus              | 1999 - 2007    | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP73 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Ford                        | Focus              | 2008 - present | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP73 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Ford                        | Fusion             | 2006 - present | n/a                                  | RP81 / RP84 / RP86                   |                                   | n/a                                  | RP71 / RP74 / RP76                   |                                   | n/a                                  | RP111 / RP115                        |                                   |
| Ford                        | Mustang            | 1994 - 2004    | RP81 / RP85                          | RP81 / RP84                          | no space for foot rest            | RP71 / RP75                          | RP71 / RP74                          | no space for foot rest            | RP113                                | RP111                                | no space for foot rest            |
| Ford                        | Mustang            | 2005 - 2009    | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP73 / RP76                   |                                   | RP114 / RP115                        | RP112 / RP115                        |                                   |
| Ford                        | Mustang *          | 2010 - present | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   | extra labor on gas pedal          | RP72 / RP75 / RP76                   | RP72 / RP73 / RP76                   | extra labor on gas pedal          | RP114 / RP115                        | RP112 / RP115                        | extra labor on gas pedal          |
| Honda                       | Accord             | 1990 - 1993    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   |                                   | RP114 / RP115                        | RP112 / RP115                        |                                   |
| Honda                       | Accord             | 1994 - 2007    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   | '94-'97 / '98-'02 / '03-'07       | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | '94-'97 / '98-'02 / '03-'07       | RP114 / RP115                        | RP112 / RP115                        | '94-'97 / '98-'02 / '03-'07       |
| Honda                       | Accord             | 2008 - present | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   |                                   | RP114 / RP115                        | RP112 / RP115                        |                                   |
| Honda                       | Civic/CR-X/Del Sol | 1988 - 2000    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   | Del Sol from '93 to '97           | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   | Del Sol from '93 to '97           | RP113 / RP115                        | RP111 / RP115                        | Del Sol from '93 to '97           |
| Honda                       | Civic              | 2001 - 2005    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Honda                       | Civic              | 2006 - present | xxx / RP85 / RP86                    | xxx / RP84 / RP86                    | gas is odd size, no fitment       | xxx / RP75 / RP76                    | xxx / RP74 / RP76                    | gas is odd size, no fitment       | n/a                                  | n/a                                  | gas is odd size, no fitment       |
| Honda                       | CR-V               | 1996 - 2001    | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   |                                      |                                      |                                   |                                      |                                      |                                   |
| Honda                       | CR-V               | 2002 - 2006    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Honda                       | Element            | 2003 - present | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Honda                       | Fit                | 2007 - 2008    | RP81 / RP85                          | RP81 / RP83                          | no space for foot rest            | RP71 / RP75                          | RP71 / RP73                          | no space for foot rest            | RP113                                | RP111                                | no space for foot rest            |
| Honda                       | Fit                | 2009 - present | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP73 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Honda                       | Insight            | 2010 - present | n/a                                  | RP81 / RP83 / RP86                   |                                   | n/a                                  | RP71 / RP73 / RP76                   |                                   | n/a                                  | RP111 / RP115                        |                                   |
| Honda                       | Odyssey            | 1995 - 1998    |                                      | RP81 / RP84 / RP86                   |                                   |                                      | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Honda                       | Odyssey            | 1999 - 2004    |                                      | RP81 / RP83 / RP86                   |                                   |                                      | RP71 / RP73 / RP76                   |                                   |                                      |                                      |                                   |
| Honda                       | Passport           | 1994 - 2002    | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP73 / RP76                   |                                   |                                      |                                      |                                   |
| Honda                       | Prelude            | 1988 - 1996    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   | '88-'91 / '92-'96                 | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | '88-'91 / '92-'96                 | RP114 / RP115                        | RP112 / RP115                        | '88-'91 / '92-'96                 |
| Honda                       | Prelude            | 1997 - 2001    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Hyundai                     | Accent             | 2008 - present | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   |                                   | RP114 / RP115                        | RP112 / RP115                        |                                   |
| Hyundai                     | Azera              | 2006 - present | n/a                                  | RP82 / RP83 / RP86                   | extra labor on gas pedal          | n/a                                  | RP72 / RP74 / RP76                   | extra labor on gas pedal          | n/a                                  | RP112 / RP115                        | extra labor on gas pedal          |
| Hyundai                     | Elantra            | 2007 - present | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Hyundai                     | Genesis Coupe *    | 2010 - present | xxx / RP85 / RP86                    | xxx / RP83 / RP86                    | gas is odd size, no fitment       | xxx / RP75 / RP76                    | xxx / RP74 / RP76                    | gas is odd size, no fitment       | n/a                                  | n/a                                  | gas is odd size, no fitment       |
| Hyundai                     | Genesis Sedan      | 2009 - present | n/a                                  | xxx / RP83 / RP86                    | gas is odd size, no fitment       | n/a                                  | xxx / RP74 / RP76                    | gas is odd size, no fitment       | n/a                                  | n/a                                  | gas is odd size, no fitment       |
| Hyundai                     | Sonata             | 2006 - present | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   | extra labor on gas pedal          | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | extra labor on gas pedal          | RP114 / RP115                        | RP112 / RP115                        | extra labor on gas pedal          |
| Hyundai                     | Tiburon            | 1997 - 2008    | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP73 / RP76                   |                                   | RP114 / RP115                        | RP112 / RP115                        |                                   |
| Infiniti                    | G20                | 1991 - 2002    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   | no G20 in '97 & '98               | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | no G20 in '97 & '98               | RP114 / RP115                        | RP112 / RP115                        | no G20 in '97 & '98               |
| Infiniti                    | G35 (V35)          | 2003 - 2007    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   |                                   | RP114 / RP115                        | RP112 / RP115                        |                                   |
| Infiniti                    | G35/G37 (V36) *    | 2007 - present | xxx / RP85 / RP86                    | xxx / RP83 / RP86                    | gas is odd size, no fitment       | xxx / RP75 / RP76                    | xxx / RP74 / RP76                    | gas is odd size, no fitment       | n/a                                  | n/a                                  | gas is odd size, no fitment       |
| Infiniti                    | I30/I35            | 1996 - 2004    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   | '96-'99 / '00-'04                 | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   | '96-'99 / '00-'04                 |                                      |                                      | '96-'99 / '00-'04                 |
| Infiniti                    | M30                | 1990 - 1992    |                                      | RP82 / RP84 / RP86                   |                                   |                                      | RP72 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Infiniti                    | M45                | 2003 - 2004    |                                      | RP82 / RP84                          |                                   |                                      | RP72 / RP74                          |                                   |                                      |                                      |                                   |
| Infiniti                    | Q45                | 1990 - 2001    | n/a                                  | RP82 / RP84                          | no space for foot rest            | n/a                                  | RP72 / RP74                          | no space for foot rest            | n/a                                  | RP112                                | no space for foot rest            |
| Infiniti                    | QX4                | 1997 - 2003    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Isuzu                       | Amigo              | 1990 - 1994    | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP73 / RP76                   |                                   |                                      |                                      |                                   |
| Isuzu                       | Amigo/Rodeo Sport  | 1998 - 2003    | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP73 / RP76                   |                                   |                                      |                                      |                                   |
| Isuzu                       | Impulse            | 1990 - 1992    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Isuzu                       | Stylus             | 1991 - 1993    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Isuzu                       | Trooper            | 1992 - 2002    | RP81 / RP85 / RP86                   | RP81 / RP84 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Isuzu                       | VehiCross          | 1999 - 2001    |                                      | RP81 / RP83 / RP86                   |                                   |                                      | RP71 / RP73 / RP76                   |                                   |                                      |                                      |                                   |
| Kia                         | Forte Sedan/Koup * | 2010 - present | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP74 / RP76                   |                                   | RP114 / RP115                        | RP112 / RP115                        |                                   |
| Kia                         | Soul               | 2010 - present | RP81 / RP85 / RP86                   | RP81 / RP83 / RP86                   |                                   | RP71 / RP75 / RP76                   | RP71 / RP73 / RP76                   |                                   | RP113 / RP115                        | RP111 / RP115                        |                                   |
| Kia                         | Spectra            | 2004 - present | RP82 / RP85 / RP86                   | RP82 / RP83 / RP86                   | foot rest n/a on Spectra 5        | RP72 / RP75 / RP76                   | RP72 / RP73 / RP76                   | foot rest n/a on Spectra 5        | RP114 / RP115                        | RP112 / RP115                        | foot rest n/a on Spectra 5        |
| Lexus                       | ES250              | 1990 - 1991    | RP82 / RP85 / RP86                   | RP82 / RP84 / RP86                   |                                   | RP72 / RP75 / RP76                   | RP72 / RP74 / RP76                   |                                   |                                      |                                      |                                   |
| Lexus                       | ES300              | 1992 - 1996    |                                      | RP82 / RP84                          | no space for foot rest?           |                                      | RP72 / RP74                          | no space for foot rest?           |                                      |                                      | no space for foot rest?           |
| Lexus                       | ES300              | 1997 - 2001    |                                      | RP81 / RP84                          | no space for foot rest?           |                                      | RP71 / RP74                          | no space for foot rest?           |                                      |                                      | no space for foot rest?           |

## GT Spec (bolt-on or drill)

## Grip Sport (bolt-on)

## LUXIS Type I (bolt-on or drill)

| Make      | Model              | Year           | GT Spec (bolt-on or drill)           |                                      | Remark                           | Grip Sport (bolt-on)      |                            | Remark                         | LUXIS Type I (bolt-on or drill)      |                                 |
|-----------|--------------------|----------------|--------------------------------------|--------------------------------------|----------------------------------|---------------------------|----------------------------|--------------------------------|--------------------------------------|---------------------------------|
|           |                    |                | Manual<br>(Accel+Brk&Clutch/Ft Rest) | Automatic<br>(Accel+Brake/Foot Rest) |                                  | Manual (Accel+Brk&Clutch) | Automatic<br>(Accel+Brake) |                                | Automatic<br>(Accel+Brake/Foot Rest) | Remark                          |
| Acura     | CL                 | 1997 - 1999    |                                      |                                      |                                  |                           | RP24                       |                                |                                      |                                 |
| Acura     | Integra            | 1990 - 2001    | RP104 / RP106                        | RP102 / RP106                        | '90-'93 / '94-'01                | RP25                      | RP23                       | '90-'93 / '94-'01              | LS202 / LS204                        | '90-'93 / '94-'01               |
| Acura     | Legend             | 1986 - 1995    |                                      |                                      | '86-'90 / '91-'95                |                           | RP24                       | '86-'90 / '91-'95              |                                      | '86-'90 / '91-'95               |
| Acura     | MDX                | 2001 - 2006    |                                      |                                      |                                  |                           | RP22                       |                                |                                      |                                 |
| Acura     | NSX                | 1991 - 2005    | RP104 / RP106                        | RP101 / RP106                        |                                  | RP25                      | RP22                       |                                | LS201 / LS204                        |                                 |
| Acura     | RDX                | 2007 - present | n/a                                  | RP103 / RP106                        |                                  | n/a                       | RP24                       |                                | LS202 / LS204                        |                                 |
| Acura     | RL                 | 1996 - 2004    |                                      | RP101                                |                                  |                           | RP23                       |                                |                                      |                                 |
| Acura     | RSX                | 2002 - 2006    | RP104 / RP106                        | RP102 / RP106                        |                                  | RP25                      | RP23                       |                                | LS202 / LS204                        |                                 |
| Acura     | SLX                | 1996 - 1999    |                                      |                                      |                                  |                           | RP23                       |                                |                                      |                                 |
| Acura     | TL                 | 1996 - 1998    |                                      | RP102 / RP106                        |                                  |                           | RP24                       |                                |                                      |                                 |
| Acura     | TL                 | 1999 - 2003    | n/a                                  | RP102 / RP106                        |                                  | n/a                       | RP24                       |                                | LS202 / LS204                        |                                 |
| Acura     | TL                 | 2004 - 2008    | n/a                                  | n/a                                  | gas is odd size, no fitment      | n/a                       | n/a                        | gas is odd size, no fitment    | LS203 / LS204                        |                                 |
| Acura     | TSX                | 2004 - 2008    | n/a                                  | n/a                                  | gas is odd size, no fitment      | n/a                       | n/a                        | gas is odd size, no fitment    | LS203 / LS204                        |                                 |
| Acura     | TSX                | 2009 - present | n/a                                  | n/a                                  | gas is odd size, no fitment      | n/a                       | n/a                        | gas is odd size, no fitment    | LS203 / LS204                        |                                 |
| Acura     | Vigor              | 1992 - 1994    |                                      |                                      |                                  |                           | RP24                       |                                |                                      |                                 |
| Chevrolet | Camaro             | 1993 - 2002    | RP105                                | RP103                                | no space for foot rest           | n/a                       | n/a                        | accel. too small               | LS202                                | no space for foot rest          |
| Chevrolet | Camaro             | 2010 - present | RP105 / RP106                        | RP103 / RP106                        | extra labor on gas pedal         | n/a                       | n/a                        | accel. too small               | n/a                                  | accel. pedal too small          |
| Chevrolet | Cavalier           | 1995 - 2005    | RP105 / RP106                        | RP103 / RP106                        |                                  | n/a                       | RP24                       | accel. too small for MT        | LS202 / LS204                        |                                 |
| Chevrolet | Cobalt             | 2005 - present | RP105 / RP106                        | RP103 / RP106                        | Supchrqd/Turbo clutch drill only | n/a                       | RP24                       | accel. too small for MT        | n/a                                  | accel. pedal too small          |
| Chevrolet | Corvette           | 1997 - present | n/a                                  | n/a                                  | metal brake&clutch, no fitment   | n/a                       | n/a                        | accel. too small               | n/a                                  | metal brake pedal, no fitment   |
| Chrysler  | 300                | 2005 - present | n/a                                  | RP103 / RP106                        | SRT model fitment not confirmed  |                           |                            |                                | LS202 / LS204                        | SRT model fitment not confirmed |
| Dodge     | Charger            | 2006 - present | n/a                                  | RP103 / RP106                        | SRT model fitment not confirmed  |                           |                            |                                | LS202 / LS204                        | SRT model fitment not confirmed |
| Dodge     | Magnum             | 2005 - 2008    | n/a                                  | RP103 / RP106                        | SRT model fitment not confirmed  |                           |                            |                                | LS202 / LS204                        | SRT model fitment not confirmed |
| Dodge     | Neon               | 1995 - 2006    | RP105 / RP106                        | RP103 / RP106                        | extra labor on SRT-4 gas pedal   | RP25                      | RP24                       | extra labor on SRT-4 gas pedal | LS202 / LS204                        |                                 |
| Ford      | Focus              | 1999 - 2007    | RP104 / RP106                        | RP101 / RP106                        |                                  | RP25                      | RP22                       |                                | LS201 / LS204                        |                                 |
| Ford      | Focus              | 2008 - present | RP104 / RP106                        | RP102 / RP106                        |                                  | RP25                      | n/a                        | brake too small for AT         | LS202 / LS204                        |                                 |
| Ford      | Fusion             | 2006 - present | n/a                                  | RP102 / RP106                        |                                  | n/a                       | n/a                        | brake too small for AT         | LS202 / LS204                        |                                 |
| Ford      | Mustang            | 1994 - 2004    | RP104                                | RP102                                | no space for foot rest           | RP25                      | RP22                       |                                | LS202                                | no space for foot rest          |
| Ford      | Mustang            | 2005 - 2009    | RP105 / RP106                        | RP103 / RP106                        |                                  | n/a                       | RP24                       | accel. too small for MT        | n/a                                  | accel. pedal too small          |
| Ford      | Mustang *          | 2010 - present | RP105 / RP106                        | RP103 / RP106                        | extra labor on gas pedal         | n/a                       | RP24                       | extra labor on gas pedal       | n/a                                  | accel. pedal too small          |
| Honda     | Accord             | 1990 - 1993    | RP105 / RP106                        | RP103 / RP106                        |                                  | RP25                      | RP24                       |                                | LS202 / LS204                        |                                 |
| Honda     | Accord             | 1994 - 2007    | RP104 / RP106                        | RP102 / RP106                        | '94-'97 / '98-'02 / '03-'07      | RP25                      | RP24                       | '94-'97 / '98-'02 / '03-'07    | LS202 / LS204                        | '94-'97 / '98-'02 / '03-'07     |
| Honda     | Accord             | 2008 - present | RP105 / RP106                        | RP103 / RP106                        |                                  | RP25                      | RP24                       |                                | LS202 / LS204                        |                                 |
| Honda     | Civic/CR-X/Del Sol | 1988 - 2000    | RP104 / RP106                        | RP102 / RP106                        | Del Sol from '93 to '97          | RP25                      | RP23                       | Del Sol from '93 to '97        | LS202 / LS204                        | Del Sol from '93 to '97         |
| Honda     | Civic              | 2001 - 2005    | RP105 / RP106                        | RP103 / RP106                        |                                  | RP25                      | RP23                       |                                | LS202 / LS204                        |                                 |
| Honda     | Civic              | 2006 - present | n/a                                  | n/a                                  | gas is odd size, no fitment      | n/a                       | n/a                        | gas is odd size, no fitment    | LS203 / LS204                        |                                 |
| Honda     | CR-V               | 1996 - 2001    |                                      |                                      |                                  |                           |                            |                                |                                      |                                 |
| Honda     | CR-V               | 2002 - 2006    |                                      |                                      |                                  |                           |                            |                                |                                      |                                 |
| Honda     | Element            | 2003 - present |                                      |                                      |                                  |                           |                            |                                |                                      |                                 |
| Honda     | Fit                | 2007 - 2008    | RP104                                | RP101                                | no space for foot rest           | RP25                      | RP22                       |                                | LS201                                | no space for foot rest          |
| Honda     | Fit                | 2009 - present | RP104 / RP106                        | RP101 / RP106                        |                                  | RP25                      | RP22                       |                                | LS201 / LS204                        |                                 |
| Honda     | Insight            | 2010 - present | n/a                                  | RP101 / RP106                        |                                  | n/a                       | RP22                       |                                | LS201 / LS204                        |                                 |
| Honda     | Odyssey            | 1995 - 1998    |                                      |                                      |                                  |                           | RP23                       |                                |                                      |                                 |
| Honda     | Odyssey            | 1999 - 2004    |                                      |                                      |                                  |                           | RP22                       |                                |                                      |                                 |
| Honda     | Passport           | 1994 - 2002    |                                      |                                      |                                  | RP25                      | RP22                       |                                |                                      |                                 |
| Honda     | Prelude            | 1988 - 1996    | RP105 / RP106                        | RP103 / RP106                        | '88-'91 / '92-'96                | RP25                      | RP24                       | '88-'91 / '92-'96              | LS202 / LS204                        | '88-'91 / '92-'96               |
| Honda     | Prelude            | 1997 - 2001    |                                      |                                      |                                  | RP25                      | RP23                       |                                |                                      |                                 |
| Hyundai   | Accent             | 2008 - present | RP104 / RP106                        | RP102 / RP106                        |                                  | n/a                       | RP24                       | accel. too small for MT        | LS202 / LS204                        |                                 |
| Hyundai   | Azera              | 2006 - present | n/a                                  | RP103 / RP106                        | extra labor on gas pedal         | n/a                       | RP24                       | extra labor on gas pedal       | n/a                                  | accel. pedal too small          |
| Hyundai   | Elantra            | 2007 - present | RP104 / RP106                        | RP102 / RP106                        |                                  | RP25                      | RP23                       |                                | LS202 / LS204                        |                                 |
| Hyundai   | Genesis Coupe *    | 2010 - present | n/a                                  | n/a                                  | gas is odd size, no fitment      | n/a                       | n/a                        | gas is odd size, no fitment    | LS203 / LS204                        |                                 |
| Hyundai   | Genesis Sedan      | 2009 - present | n/a                                  | n/a                                  | gas is odd size, no fitment      | n/a                       | n/a                        | gas is odd size, no fitment    | LS203 / LS204                        |                                 |
| Hyundai   | Sonata             | 2006 - present | RP105 / RP106                        | RP103 / RP106                        | extra labor on gas pedal         | n/a                       | RP24                       | accel. too small for MT        | n/a                                  | accel. pedal too small          |
| Hyundai   | Tiburon            | 1997 - 2008    | RP105 / RP106                        | RP103 / RP106                        |                                  | n/a                       | RP24                       | accel. too small for MT        | n/a                                  | accel. pedal too small          |
| Infiniti  | G20                | 1991 - 2002    | RP104 / RP106                        | RP102 / RP106                        | no G20 in '97 & '98              | RP25                      | RP24                       | no G20 in '97 & '98            | LS202 / LS204                        | no G20 in '97 & '98             |
| Infiniti  | G35 (V35)          | 2003 - 2007    | RP105 / RP106                        | RP103 / RP106                        |                                  | RP25                      | RP24                       |                                | LS202 / LS204                        |                                 |
| Infiniti  | G35/G37 (V36) *    | 2007 - present | n/a                                  | n/a                                  | gas is odd size, no fitment      | n/a                       | n/a                        | gas is odd size, no fitment    | LS203 / LS204                        |                                 |
| Infiniti  | I30/I35            | 1996 - 2004    |                                      |                                      | '96-'99 / '00-'04                |                           | RP24                       |                                |                                      | '96-'99 / '00-'04               |
| Infiniti  | M30                | 1990 - 1992    |                                      |                                      |                                  |                           | RP24                       |                                |                                      |                                 |
| Infiniti  | M45                | 2003 - 2004    |                                      |                                      |                                  |                           | RP24                       |                                |                                      |                                 |
| Infiniti  | Q45                | 1990 - 2001    | n/a                                  | RP103                                | no space for foot rest           | n/a                       | RP24                       |                                | LS202                                | no space for foot rest          |
| Infiniti  | QX4                | 1997 - 2003    |                                      |                                      |                                  |                           | RP24                       |                                |                                      |                                 |
| Isuzu     | Amigo              | 1990 - 1994    |                                      |                                      |                                  | RP25                      | RP22                       |                                |                                      |                                 |
| Isuzu     | Amigo/Rodeo Sport  | 1998 - 2003    |                                      |                                      |                                  | RP25                      | RP22                       |                                |                                      |                                 |
| Isuzu     | Impulse            | 1990 - 1992    |                                      |                                      |                                  | RP25                      | RP23                       |                                |                                      |                                 |
| Isuzu     | Stylus             | 1991 - 1993    |                                      |                                      |                                  | RP25                      | RP23                       |                                |                                      |                                 |
| Isuzu     | Trooper            | 1992 - 2002    |                                      |                                      |                                  | RP25                      | RP23                       |                                |                                      |                                 |
| Isuzu     | VehiCross          | 1999 - 2001    |                                      |                                      |                                  |                           | RP22                       |                                |                                      |                                 |
| Kia       | Forte Sedan/Koup * | 2010 - present | RP105 / RP106                        | RP103 / RP106                        |                                  | RP25                      | RP23                       |                                | LS202 / LS204                        |                                 |
| Kia       | Soul               | 2010 - present | RP104 / RP106                        | RP101 / RP106                        |                                  | RP25                      | RP22                       |                                | LS202 / LS204                        |                                 |
| Kia       | Spectra            | 2004 - present | RP105 / RP106                        | RP103 / RP106                        | foot rest n/a on Spectra 5       | n/a                       | RP24                       | accel. too small for MT        | n/a                                  | accel. pedal too small          |
| Lexus     | ES250              | 1990 - 1991    |                                      |                                      |                                  |                           | RP24                       |                                |                                      |                                 |
| Lexus     | ES300              | 1992 - 1996    |                                      | RP103                                | no space for foot rest?          |                           | RP24                       | no space for foot rest?        |                                      | no space for foot rest?         |
| Lexus     | ES300              | 1997 - 2001    |                                      | RP103                                | no space for foot rest?          |                           | RP23                       | no space for foot rest?        |                                      | no space for foot rest?         |

## Competition Sport (bolt-on)

## Executive Sport (bolt-on)

## Formula Spec (bolt-on or drill)

| Make       | Model                    | Year           | Competition Sport (bolt-on)        |                                      | Remark                           | Executive Sport (bolt-on)          |                                      | Remark                           | Formula Spec (bolt-on or drill)    |                                      | Remark                        |
|------------|--------------------------|----------------|------------------------------------|--------------------------------------|----------------------------------|------------------------------------|--------------------------------------|----------------------------------|------------------------------------|--------------------------------------|-------------------------------|
|            |                          |                | Manual<br>(Accel/Brk&Clch/Ft Rest) | Automatic<br>(Accel/Brake/Foot Rest) |                                  | Manual<br>(Accel/Brk&Clch/Ft Rest) | Automatic<br>(Accel/Brake/Foot Rest) |                                  | Manual<br>(Accel/Brk&Clch/Ft Rest) | Automatic<br>(Accel/Brake/Foot Rest) |                               |
| Lexus      | ES300/330                | 2002 - 2006    |                                    | RP81 / RP83 / RP86                   |                                  | RP71 / RP74 / RP76                 |                                      |                                  |                                    |                                      |                               |
| Lexus      | GS300/400/430            | 1993 - 2005    | n/a                                | RP82 / RP84 / RP86                   | GS400 '98- /GS430 '01-           | n/a                                | RP72 / RP74 / RP76                   | GS400 '98- /GS430 '01-           | n/a                                | RP112 / RP115                        | GS400 '98- /GS430 '01-        |
| Lexus      | GS300/350/430/460        | 2006 - present | n/a                                | xxx / RP83 / RP86                    | gas is odd size, no fitment      | n/a                                | xxx / RP73 / RP76                    | gas is odd size, no fitment      | n/a                                | n/a                                  | gas is odd size, no fitment   |
| Lexus      | GX470                    | 2003 - 2009    |                                    | RP81 / RP83 / RP86                   |                                  | RP71 / RP74 / RP76                 |                                      |                                  |                                    |                                      |                               |
| Lexus      | IS300                    | 2000 - 2005    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Lexus      | IS250/350                | 2006 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Lexus      | LX450/470                | 1996 - 2007    |                                    | RP81 / RP84 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Lexus      | RX300                    | 1999 - 2003    |                                    | RP82 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Lexus      | SC300/400                | 1992 - 2001    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Lexus      | SC430                    | 2002 - present |                                    | RP81 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Mazda      | 323 / Protégé            | 1989 - 1998    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   | '89-'94 / '95-'98                | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   | '89-'94 / '95-'98                |                                    |                                      | '89-'94 / '95-'98             |
| Mazda      | Protégé/Protégé 5        | 1999 - 2003    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Mazda      | 3                        | 2004 - 2009    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Mazda      | 3                        | 2010 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | Mazdaspeed3 no fitment           | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   | Mazdaspeed3 no fitment           | RP113 / RP115                      | RP111 / RP115                        | Mazdaspeed3 no fitment        |
| Mazda      | MX-3                     | 1992 - 1995    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Mazda      | 626                      | 1989 - 1992    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Mazda      | 626                      | 1993 - 1997    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Mazda      | 6                        | 2003 - 2008    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   | Mazdaspeed6 OK                   | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   | Mazdaspeed6 OK                   | RP113 / RP115                      | RP111 / RP115                        | Mazdaspeed6 OK                |
| Mazda      | MX-6                     | 1993 - 1997    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Mazda      | CX-7                     | 2007 - present | n/a                                | RP81 / RP84 / RP86                   | extra labor on gas pedal         | n/a                                | RP71 / RP74 / RP76                   | extra labor on gas pedal         | n/a                                | RP112 / RP115                        | extra labor on gas pedal      |
| Mazda      | MPV                      | 2000 - 2006    |                                    | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Mazda      | MX-5 Miata               | 1990 - 1998    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP75 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Mazda      | MX-5 Miata               | 1999 - 2005    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   | Mazdaspeed MX-5 no fitment       | RP72 / RP75 / RP76                 | RP72 / RP75 / RP76                   | Mazdaspeed MX-5 no fitment       | RP114 / RP115                      | RP112 / RP115                        | Mazdaspeed MX-5 no fitment    |
| Mazda      | MX-5 Miata               | 2006 - present | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Mazda      | RX-7                     | 1986 - 1991    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   | no RX-7 released for '92         | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | no RX-7 released for '92         | RP114 / RP115                      | RP112 / RP115                        | no RX-7 released for '92      |
| Mazda      | RX-7                     | 1993 - 1995    | RP82 / xxx /RP86                   | RP82 / RP83 / RP86                   | MT brake&clutch metal, no fit    | RP72 / xxx /RP76                   | RP72 / RP73 / RP76                   | MT brake&clutch metal, no fit    | n/a                                | RP112 / RP115                        | MT brake&clutch metal, no fit |
| Mazda      | RX-8                     | 2003 - present | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Mazda      | Tibute                   | 2001 - 2007    |                                    | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Mitsubishi | Diamante                 | 1992 - 1995    | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Mitsubishi | Eclipse                  | 1990 - 1999    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   | '90-'94 / '95-'99                | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | '90-'94 / '95-'99                | RP114 / RP115                      | RP112 / RP115                        | '90-'94 / '95-'99             |
| Mitsubishi | Eclipse                  | 2000 - 2005    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Mitsubishi | Eclipse                  | 2006 - present | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Mitsubishi | Expo                     | 1992 - 1995    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Mitsubishi | Lancer/Evolution         | 2002 - 2007    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | Lancer Evolution from '03        | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | Lancer Evolution from '03        | RP113 / RP115                      | RP111 / RP115                        | Lancer Evolution from '03     |
| Mitsubishi | Lancer/Evolution *       | 2008 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | extra labor on gas pedal         | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | extra labor on gas pedal         | RP113 / RP115                      | RP111 / RP115                        | extra labor on gas pedal      |
| Mitsubishi | Mirage                   | 1997 - 2002    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Mitsubishi | Outlander                | 2007 - present | n/a                                | RP81 / RP83 / RP86                   | extra labor on gas pedal         | n/a                                | RP71 / RP73 / RP76                   | extra labor on gas pedal         | n/a                                | RP111 / RP115                        | extra labor on gas pedal      |
| Mitsubishi | 3000GT                   | 1991 - 1998    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Nissan     | 240SX                    | 1989 - 1998    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Nissan     | 300ZX                    | 1984 - 1996    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Nissan     | 350Z                     | 2003 - 2008    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Nissan     | 370Z                     | 2009 - present | xxx / RP85 / RP86                  | xxx / RP84 / RP86                    | gas no fit, extra labor MT brake | xxx / RP75 / RP76                  | xxx / RP74 / RP76                    | gas no fit, extra labor MT brake | n/a                                | n/a                                  | gas is odd size, no fitment   |
| Nissan     | Altima                   | 1997 - 2001    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Nissan     | Altima                   | 2002 - 2006    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   | extra labor for accel.           | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   | extra labor for accel.           | RP113 / RP115                      | RP111 / RP115                        | extra labor for accel.        |
| Nissan     | Altima                   | 2007 - present | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   | gas on Hybrid no fit             | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   | gas on Hybrid no fitment         | RP113 / RP115                      | RP111 / RP115                        | Hybrid gas pedal drill only   |
| Nissan     | Altima Coupe             | 2008 - present | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Nissan     | Cube                     | 2009 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Nissan     | Hardbody Pickup          | 1986 - 1997    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Nissan     | Frontier                 | 1998 - 2004    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Nissan     | Maxima                   | 1989 - 2003    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Nissan     | Murano                   | 2009 - present | n/a                                | RP81 / RP84 / RP86                   | extra labor on gas pedal         | n/a                                | RP71 / RP74 / RP76                   | extra labor on gas pedal         | n/a                                | RP111 / RP115                        | extra labor on gas pedal      |
| Nissan     | Pathfinder               | 1986 - 2004    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   | '86-'95 / '96-'04                | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | '86-'95 / '96-'04                |                                    |                                      | '86-'95 / '96-'04             |
| Nissan     | Rogue                    | 2008 - present | n/a                                | RP81 / RP84 / RP86                   | extra labor on gas pedal         | n/a                                | RP71 / RP74 / RP76                   | extra labor on gas pedal         | n/a                                | RP111 / RP115                        | extra labor on gas pedal      |
| Nissan     | Sentra                   | 1986 - 1990    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Nissan     | Sentra/200SX/SE-R        | 1991 - 2006    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Nissan     | Sentra/SE-R *            | 2007 - present | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Nissan     | Skyline GT-R (R32/33/34) | 1989 - 2002    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   | non GT-R models OK               | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | non GT-R models OK               | RP114 / RP115                      | RP112 / RP115                        | non GT-R models OK            |
| Nissan     | Versa                    | 2007 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Saturn     | Ion/Ion Redline          | 2003 - 2007    | RP82 / RP85                        | RP82 / RP83                          | no space for foot rest           | RP72 / RP75                        | RP72 / RP73                          | no space for foot rest           | RP114                              | RP112                                | no space for foot rest        |
| Scion      | xA                       | 2003 - 2007    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Scion      | xB                       | 2003 - 2007    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Scion      | xB                       | 2008 - present | xxx / RP85 / RP86                  | xxx / RP83 / RP86                    | gas is odd size, no fitment      | xxx / RP75 / RP76                  | xxx / RP73 / RP76                    | gas is odd size, no fitment      | RP113 / RP115                      | RP111 / RP115                        | gas pedal drill only          |
| Scion      | tC                       | 2005 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Scion      | xD                       | 2008 - present | xxx / xxx / RP86                   | xxx / RP83 / RP86                    | gas&clutch odd size, no fitment  | xxx / xxx / RP76                   | xxx / RP73 / RP76                    | gas&clutch odd size, no fitment  | RP113 / RP115                      | RP111 / RP115                        | gas&clutch drill only         |
| Subaru     | Forester                 | 1998 - 2002    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  |                                    |                                      |                               |
| Subaru     | Forester                 | 2003 - 2008    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Subaru     | Impreza                  | 1994 - 2001    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   |                                  | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   |                                  | RP114 / RP115                      | RP112 / RP115                        |                               |
| Subaru     | Impreza/STi              | 2002 - 2007    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | STi from '04                     | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | STi from '04                     | RP113 / RP115                      | RP111 / RP115                        | STi from '04                  |
| Subaru     | Impreza                  | 2008 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | extra labor on gas pedal         | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | extra labor on gas pedal         | RP113 / RP115                      | RP111 / RP115                        | extra labor on gas pedal      |
| Subaru     | Legacy                   | 1990 - 2004    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   | '90-'94 / '95-'99 / '00-'04      | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | '90-'94 / '95-'99 / '00-'04      |                                    |                                      | '90-'94 / '95-'99 / '00-'04   |
| Subaru     | Legacy                   | 2005 - 2009    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  | RP113 / RP115                      | RP111 / RP115                        |                               |
| Subaru     | SVX                      | 1992 - 1997    |                                    | RP82 / RP84                          |                                  |                                    | RP72 / RP74                          |                                  |                                    |                                      |                               |
| Suzuki     | Aerio                    | 2002 - 2007    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Suzuki     | Samurai                  | 1986 - 1995    | RP81 / RP85                        | RP81 / RP83                          |                                  | RP71 / RP75                        | RP71 / RP73                          |                                  |                                    |                                      |                               |
| Suzuki     | Sidekick                 | 1989 - 1998    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Suzuki     | Swift                    | 1989 - 1991    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Suzuki     | SX4                      | 2007 - present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | extra labor on gas pedal         | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | extra labor on gas pedal         | RP113 / RP115                      | RP111 / RP115                        | extra labor on gas pedal      |
| Suzuki     | Vitara                   | 1999 - 2005    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |
| Suzuki     | X-90                     | 1996 - 1998    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                                  |                                    |                                      |                               |

## GT Spec (bolt-on or drill)

## Grip Sport (bolt-on)

## LUXIS Type I (bolt-on or drill)

| Make       | Model                    | Year           | GT Spec (bolt-on or drill)         |                                      | Remark                          | Grip Sport (bolt-on)    |                            | Remark                      | LUXIS Type I (bolt-on or drill)      |                             | Remark                       |
|------------|--------------------------|----------------|------------------------------------|--------------------------------------|---------------------------------|-------------------------|----------------------------|-----------------------------|--------------------------------------|-----------------------------|------------------------------|
|            |                          |                | Manual<br>(Accel+Brk&Clch/Ft Rest) | Automatic<br>(Accel+Brake/Foot Rest) |                                 | Manual (Accel+Brk&Clch) | Automatic<br>(Accel+Brake) |                             | Automatic<br>(Accel+Brake/Foot Rest) |                             |                              |
| Lexus      | ES300/330                | 2002 - 2006    |                                    | RP103 / RP106                        |                                 |                         | RP23                       |                             |                                      |                             |                              |
| Lexus      | GS300/400/430            | 1993 - 2005    | n/a                                | RP103 / RP106                        | GS400 '98- /GS430 '01-          | n/a                     | RP24                       | GS400 '98- /GS430 '01-      | LS202 / LS204                        | GS400 '98- /GS430 '01-      |                              |
| Lexus      | GS300/350/430/460        | 2006 - present | n/a                                | n/a                                  | gas is odd size, no fitment     | n/a                     | n/a                        | gas is odd size, no fitment | LS203 / LS204                        |                             |                              |
| Lexus      | GX470                    | 2003 - 2009    |                                    |                                      |                                 |                         | RP22                       |                             |                                      |                             |                              |
| Lexus      | IS300                    | 2000 - 2005    | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | RP23                        | LS202 / LS204                        |                             |                              |
| Lexus      | IS250/350                | 2006 - present | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP23                        | LS202 / LS204                        |                             |                              |
| Lexus      | LX450/470                | 1996 - 2007    |                                    |                                      |                                 |                         |                            | RP23                        |                                      |                             |                              |
| Lexus      | RX300                    | 1999 - 2003    |                                    |                                      |                                 |                         |                            |                             |                                      |                             |                              |
| Lexus      | SC300/400                | 1992 - 2001    | RP105 / RP106                      | RP103 / RP106                        |                                 | n/a                     | RP24                       |                             | LS202 / LS204                        |                             |                              |
| Lexus      | SC430                    | 2002 - present |                                    | RP103 / RP106                        |                                 |                         | RP23                       |                             |                                      |                             |                              |
| Mazda      | 323 / Protégé            | 1989 - 1998    |                                    |                                      | '89-'94 / '95-'98               |                         |                            | '89-'94 / '95-'98           |                                      | '89-'94 / '95-'98           |                              |
| Mazda      | Protégé/Protégé 5        | 1999 - 2003    | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP23                        | LS201 / LS204                        |                             |                              |
| Mazda      | 3                        | 2004 - 2009    | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP23                        | LS201 / LS204                        |                             |                              |
| Mazda      | 3                        | 2010 - present | RP104 / RP106                      | RP102 / RP106                        | Mazdaspeed3 no fitment          |                         | RP25                       | n/a                         | brake too small for AT               | LS202 / LS204               |                              |
| Mazda      | MX-3                     | 1992 - 1995    |                                    |                                      |                                 |                         |                            |                             |                                      |                             |                              |
| Mazda      | 626                      | 1989 - 1992    |                                    |                                      |                                 |                         | RP25                       | RP24                        |                                      |                             |                              |
| Mazda      | 626                      | 1993 - 1997    |                                    |                                      |                                 |                         | RP25                       | RP23                        |                                      |                             |                              |
| Mazda      | 6                        | 2003 - 2008    | RP104 / RP106                      | RP102 / RP106                        | Mazdaspeed6 OK                  |                         | RP25                       | RP23                        | Mazdaspeed6 OK                       | LS202 / LS204               |                              |
| Mazda      | MX-6                     | 1993 - 1997    |                                    |                                      |                                 |                         | RP25                       | RP23                        |                                      |                             |                              |
| Mazda      | CX-7                     | 2007 - present | n/a                                | RP103 / RP106                        | extra labor on gas pedal        | n/a                     | n/a                        | n/a                         | brake too small for AT               | LS202 / LS204               | extra labor on gas pedal     |
| Mazda      | MPV                      | 2000 - 2006    |                                    |                                      |                                 |                         |                            | RP22                        |                                      |                             |                              |
| Mazda      | MX-5 Miata               | 1990 - 1998    | RP105 / RP106                      | RP103 / RP106                        |                                 |                         | RP25                       | RP22                        | LS201 / LS204                        |                             |                              |
| Mazda      | MX-5 Miata               | 1999 - 2005    | RP105 / RP106                      | RP103 / RP106                        | Mazdaspeed MX-5 no fitment      |                         | n/a                        | RP24                        | accel. too small for MT              | LS201 / LS204               |                              |
| Mazda      | MX-5 Miata               | 2006 - present | RP105 / RP106                      | RP103 / RP106                        |                                 |                         | n/a                        | RP24                        | accel. too small for MT              | n/a                         | accel. pedal too small       |
| Mazda      | RX-7                     | 1986 - 1991    | RP105 / RP106                      | RP103 / RP106                        | no RX-7 released for '92        |                         | RP25                       | RP24                        | no RX-7 released for '92             | LS202 / LS204               | no RX-7 released for '92     |
| Mazda      | RX-7                     | 1993 - 1995    | n/a                                | RP101 / RP106                        | MT brake&clutch metal, no fit   |                         | n/a                        | RP23                        | MT brake&clutch metal, no fit        | LS202 / LS204               |                              |
| Mazda      | RX-8                     | 2003 - present | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP23                        | LS202 / LS204                        |                             |                              |
| Mazda      | Tibute                   | 2001 - 2007    |                                    |                                      |                                 |                         |                            | RP22                        |                                      |                             |                              |
| Mitsubishi | Diamante                 | 1992 - 1995    |                                    |                                      |                                 |                         |                            |                             |                                      |                             |                              |
| Mitsubishi | Eclipse                  | 1990 - 1999    | RP105 / RP106                      | RP103 / RP106                        | '90-'94 / '95-'99               |                         | RP25                       | RP23                        | LS202 / LS204                        | '90-'94 / '95-'99           |                              |
| Mitsubishi | Eclipse                  | 2000 - 2005    | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | RP23                        | LS201 / LS204                        |                             |                              |
| Mitsubishi | Eclipse                  | 2006 - present | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | RP23                        | LS202 / LS204                        |                             |                              |
| Mitsubishi | Expo                     | 1992 - 1995    |                                    |                                      |                                 |                         |                            | RP24                        |                                      |                             |                              |
| Mitsubishi | Lancer/Evolution         | 2002 - 2007    | RP104 / RP106                      | RP101 / RP106                        | Lancer Evolution from '03       |                         | RP25                       | RP22                        | Lancer Evolution from '03            | LS202 / LS204               |                              |
| Mitsubishi | Lancer/Evolution *       | 2008 - present | RP104 / RP106                      | RP101 / RP106                        | extra labor on gas pedal        |                         | RP25                       | RP23                        | extra labor on gas pedal             | LS202 / LS204               | extra labor on gas pedal     |
| Mitsubishi | Mirage                   | 1997 - 2002    | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP22                        | LS201 / LS204                        |                             |                              |
| Mitsubishi | Outlander                | 2007 - present | n/a                                | RP101 / RP106                        | extra labor on gas pedal        | n/a                     | RP23                       | RP23                        | extra labor on gas pedal             | LS202 / LS204               | extra labor on gas pedal     |
| Mitsubishi | 3000GT                   | 1991 - 1998    | RP105 / RP106                      | RP103 / RP106                        |                                 |                         | RP25                       | RP24                        | LS202 / LS204                        |                             |                              |
| Nissan     | 240SX                    | 1989 - 1998    | RP105 / RP106                      | RP103 / RP106                        |                                 |                         | RP25                       | RP24                        | LS202 / LS204                        |                             |                              |
| Nissan     | 300ZX                    | 1984 - 1996    | RP105 / RP106                      | RP103 / RP106                        |                                 |                         | RP25                       | RP24                        | LS202 / LS204                        |                             |                              |
| Nissan     | 350Z                     | 2003 - 2008    | RP105 / RP106                      | RP103 / RP106                        |                                 | n/a                     | RP24                       |                             | n/a                                  | accel. pedal too small      |                              |
| Nissan     | 370Z                     | 2009 - present | n/a                                | n/a                                  | gas is odd size, no fitment     | n/a                     | n/a                        | n/a                         | gas is odd size, no fitment          | LS203 / LS204               |                              |
| Nissan     | Altima                   | 1997 - 2001    | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | RP24                        | LS202 / LS204                        |                             |                              |
| Nissan     | Altima                   | 2002 - 2006    | RP104 / RP106                      | RP102 / RP106                        | extra labor for accel.          |                         | RP25                       | RP23                        | LS202 / LS204                        | extra labor for accel.      | extra labor for accel.       |
| Nissan     | Altima                   | 2007 - present | RP104 / RP106                      | RP102 / RP106                        | no fitment for Hybrid           |                         | RP25                       | n/a                         | brake too small for AT               | LS202 / LS204               | accel. for Hybrid drill only |
| Nissan     | Altima Coupe             | 2008 - present | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | n/a                         | brake too small for AT               | LS202 / LS204               |                              |
| Nissan     | Cube                     | 2009 - present | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | RP23                        | LS202 / LS204                        |                             |                              |
| Nissan     | Hardbody Pickup          | 1986 - 1997    |                                    |                                      |                                 |                         |                            | RP24                        |                                      |                             |                              |
| Nissan     | Frontier                 | 1998 - 2004    |                                    |                                      |                                 |                         |                            | RP24                        |                                      |                             |                              |
| Nissan     | Maxima                   | 1989 - 2003    | RP105 / RP106                      | RP103 / RP106                        |                                 |                         | RP25                       | RP24                        | LS202 / LS204                        |                             |                              |
| Nissan     | Murano                   | 2009 - present | n/a                                | RP102 / RP106                        | extra labor on gas pedal        | n/a                     | n/a                        | n/a                         | brake too small for AT               | LS202 / LS204               | extra labor on gas pedal     |
| Nissan     | Pathfinder               | 1986 - 2004    |                                    |                                      | '86-'95 / '96-'04               |                         |                            | RP24                        | '86-'95 / '96-'04                    | '86-'95 / '96-'04           |                              |
| Nissan     | Rogue                    | 2008 - present | n/a                                | RP102 / RP106                        | extra labor on gas pedal        | n/a                     | n/a                        | n/a                         | brake too small for AT               | LS202 / LS204               | extra labor on gas pedal     |
| Nissan     | Sentra                   | 1986 - 1990    |                                    |                                      |                                 |                         |                            | RP24                        |                                      |                             |                              |
| Nissan     | Sentra/200SX/SE-R        | 1991 - 2006    | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | RP24                        | LS202 / LS204                        |                             |                              |
| Nissan     | Sentra/SE-R *            | 2007 - present | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | n/a                         | brake too small for AT               | LS202 / LS204               |                              |
| Nissan     | Skyline GT-R (R32/33/34) | 1989 - 2002    | RP105 / RP106                      | RP103 / RP106                        | non GT-R models OK              |                         | RP25                       | RP24                        | LS202 / LS204                        | non GT-R models OK          | non GT-R models OK           |
| Nissan     | Versa                    | 2007 - present | RP104 / RP106                      | RP102 / RP106                        |                                 |                         | RP25                       | RP23                        | LS202 / LS204                        |                             |                              |
| Saturn     | Ion/Ion Redline          | 2003 - 2007    | RP105                              | RP103                                | no space for foot rest          | n/a                     | RP24                       |                             | accel. too small for MT              | n/a                         | accel. pedal too small       |
| Scion      | xA                       | 2003 - 2007    | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP22                        | LS201 / LS204                        |                             |                              |
| Scion      | xB                       | 2003 - 2007    | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP22                        | LS201 / LS204                        |                             |                              |
| Scion      | xB                       | 2008 - present | n/a                                | n/a                                  | gas is odd size, no fitment     | n/a                     | n/a                        | n/a                         | gas is odd size, no fitment          | LS201 / LS204               | gas pedal drill only         |
| Scion      | tC                       | 2005 - present | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP22                        | LS201 / LS204                        |                             |                              |
| Scion      | xD                       | 2008 - present | n/a                                | n/a                                  | gas&clutch odd size, no fitment | n/a                     | n/a                        | n/a                         | gas&clutch odd size, no fitment      | LS201 / LS204               | gas pedal drill only         |
| Subaru     | Forester                 | 1998 - 2002    |                                    |                                      |                                 |                         |                            | RP24                        |                                      |                             |                              |
| Subaru     | Forester                 | 2003 - 2008    |                                    |                                      |                                 |                         | RP25                       | RP22                        |                                      |                             |                              |
| Subaru     | Impreza                  | 1994 - 2001    | RP105 / RP106                      | RP103 / RP106                        |                                 |                         | RP25                       | RP24                        | LS202 / LS204                        |                             |                              |
| Subaru     | Impreza/STi              | 2002 - 2007    | RP104 / RP106                      | RP101 / RP106                        | STi from '04                    |                         | RP25                       | RP22                        | LS202 / LS204                        |                             |                              |
| Subaru     | Impreza                  | 2008 - present | RP104 / RP106                      | RP101 / RP106                        | extra labor on gas pedal        |                         | RP25                       | RP22                        | LS202 / LS204                        | extra labor on gas pedal    | extra labor on gas pedal     |
| Subaru     | Legacy                   | 1990 - 2004    |                                    |                                      | '90-'94 / '95-'99 / '00-'04     |                         |                            | RP24                        | '90-'94 / '95-'99 / '00-'04          | '90-'94 / '95-'99 / '00-'04 |                              |
| Subaru     | Legacy                   | 2005 - 2009    | RP104 / RP106                      | RP101 / RP106                        |                                 |                         | RP25                       | RP22                        | LS202 / LS204                        |                             |                              |
| Subaru     | SVX                      | 1992 - 1997    |                                    |                                      |                                 |                         |                            | RP24                        |                                      |                             |                              |
| Suzuki     | Aerio                    | 2002 - 2007    |                                    |                                      |                                 |                         | RP25                       | RP22                        |                                      |                             |                              |
| Suzuki     | Samurai                  | 1986 - 1995    |                                    |                                      |                                 |                         | RP25                       | RP22                        |                                      |                             |                              |
| Suzuki     | Sidekick                 | 1989 - 1998    |                                    |                                      |                                 |                         | RP25                       | RP22                        |                                      |                             |                              |
| Suzuki     | Swift                    | 1989 - 1991    |                                    |                                      |                                 |                         | RP25                       | RP22                        |                                      |                             |                              |
| Suzuki     | SX4                      | 2007 - present | RP104 / RP106                      | RP101 / RP106                        | extra labor on gas pedal        |                         | RP25                       | RP22                        | LS202 / LS204                        | extra labor on gas pedal    | extra labor on gas pedal     |
| Suzuki     | Vitara                   | 1999 - 2005    |                                    |                                      |                                 |                         | RP25                       | RP22                        |                                      |                             |                              |
| Suzuki     | X-90                     | 1996 - 1998    |                                    |                                      |                                 |                         | RP25                       | RP22                        |                                      |                             |                              |

| Make   | Model               | Year           | Competition Sport (bolt-on)        |                                      |                               | Executive Sport (bolt-on)          |                                      |                               | Formula Spec (bolt-on or drill)    |                                      |                               |
|--------|---------------------|----------------|------------------------------------|--------------------------------------|-------------------------------|------------------------------------|--------------------------------------|-------------------------------|------------------------------------|--------------------------------------|-------------------------------|
|        |                     |                | Manual<br>(Accel/Brk&Clch/Ft Rest) | Automatic<br>(Accel/Brake/Foot Rest) | Remark                        | Manual<br>(Accel/Brk&Clch/Ft Rest) | Automatic<br>(Accel/Brake/Foot Rest) | Remark                        | Manual<br>(Accel+Brk&Clch/Ft Rest) | Automatic<br>(Accel+Brake/Foot Rest) | Remark                        |
| Toyota | 4Runner             | 1984 – 1989    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                               | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                               |                                    |                                      |                               |
| Toyota | 4Runner             | 1990 – 1995    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                               | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                               |                                    |                                      |                               |
| Toyota | 4Runner             | 1996 – 2002    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                               | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                               |                                    |                                      |                               |
| Toyota | 4Runner             | 2003 – present | n/a                                | RP81 / RP83 / RP86                   | extra labor on gas pedal      | n/a                                | RP71 / RP73 / RP76                   | extra labor on gas pedal      | n/a                                | RP111 / RP115                        | extra labor on gas pedal      |
| Toyota | Avalon              | 1995 – 2004    |                                    | RP82 / RP84                          | '95-'99 / '00-'04             |                                    | RP72 / RP74                          | '95-'99 / '00-'04             |                                    |                                      | '95-'99 / '00-'04             |
| Toyota | Camry               | 1992 – 1996    |                                    | RP82 / RP84                          |                               |                                    | RP72 / RP74                          |                               |                                    |                                      |                               |
| Toyota | Camry               | 1997 – 2001    |                                    | RP81 / RP84 / RP86                   |                               |                                    | RP71 / RP74 / RP76                   |                               |                                    |                                      |                               |
| Toyota | Camry               | 2002 – 2006    |                                    | RP81 / RP83 / RP86                   |                               |                                    | RP71 / RP74 / RP76                   |                               |                                    |                                      |                               |
| Toyota | Camry               | 2007 – present | n/a                                | RP82 / RP83 / RP86                   | extra labor on gas pedal      | n/a                                | RP72 / RP73 / RP76                   | extra labor on gas pedal      | n/a                                | RP112 / RP115                        | extra labor on gas pedal      |
| Toyota | Celica              | 1986 – 1999    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   | '86-'89 / '90-'99             | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | '86-'89 / '90-'99             |                                    |                                      | '86-'89 / '90-'99             |
| Toyota | Celica              | 2000 – 2005    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   |                               | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   |                               | RP114 / RP115                      | RP112 / RP115                        |                               |
| Toyota | Corolla GT-S (AE86) | 1984 – 1987    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | SR5 model OK                  | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | SR5 model OK                  | RP113 / RP115                      | RP111 / RP115                        | SR5 model OK                  |
| Toyota | Corolla             | 1988 – 1992    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                               | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   |                               |                                    |                                      |                               |
| Toyota | Corolla             | 1993 – 2008    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | '93-'97 / '98-'02 / '03-'08   | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | '93-'97 / '98-'02 / '03-'08   |                                    |                                      | '93-'97 / '98-'02 / '03-'08   |
| Toyota | Corolla             | 2009 – present | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   | extra labor on gas & MT brake | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   | extra labor on gas & MT brake | RP114 / RP115                      | RP112 / RP115                        | extra labor on gas & MT brake |
| Toyota | Cressida            | 1985 – 1992    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   | '85-'88 / '89-'92             | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | '85-'88 / '89-'92             |                                    |                                      | '85-'88 / '89-'92             |
| Toyota | Echo                | 2000 – 2005    | RP81 / RP85                        | RP81 / RP83                          |                               | RP71 / RP75                        | RP71 / RP73                          |                               |                                    |                                      |                               |
| Toyota | Land Cruiser        | 1991 – 2007    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   | '91-'97 / '98-'07             | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   | '91-'97 / '98-'07             |                                    |                                      | '91-'97 / '98-'07             |
| Toyota | Matrix              | 2003 – 2008    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                               | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                               | RP113 / RP115                      | RP111 / RP115                        |                               |
| Toyota | Matrix              | 2009 – present | RP82 / RP85 / RP86                 | RP82 / RP83 / RP86                   | extra labor on gas & MT brake | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   | extra labor on gas & MT brake | RP114 / RP115                      | RP112 / RP115                        | extra labor on gas & MT brake |
| Toyota | MR-2                | 1985 – 1996    | RP81 / RP83 / RP86                 | RP81 / RP83 / RP86                   | '85-'89 / '90-'96             | RP71 / RP73 / RP76                 | RP71 / RP73 / RP76                   | '85-'89 / '90-'96             | RP113 / RP115                      | RP111 / RP115                        | '85-'89 / '90-'96             |
| Toyota | MR-2 Spyder         | 2000 – 2005    | RP81 / RP83 / RP86                 | RP81 / RP83 / RP86                   |                               | RP71 / RP73 / RP76                 | RP71 / RP73 / RP76                   |                               | RP113 / RP115                      | RP111 / RP115                        |                               |
| Toyota | Previa              | 1991 – 1997    |                                    | RP81 / RP83 / RP86                   |                               |                                    | RP71 / RP73 / RP75                   |                               |                                    |                                      |                               |
| Toyota | Prius               | 2001 – 2009    |                                    | RP81 / RP83 / RP86                   | '01-'03 / '04-'09             |                                    | RP71 / RP73 / RP75                   | '01-'03 / '04-'09             |                                    |                                      | '01-'03 / '04-'09             |
| Toyota | RAV4                | 1996 – 2005    | RP81 / RP85 / RP86                 | RP81 / RP84 / RP86                   | '96-'00 / '01-'05             | RP71 / RP75 / RP76                 | RP71 / RP74 / RP76                   | '96-'00 / '01-'05             |                                    |                                      | '96-'00 / '01-'05             |
| Toyota | Supra               | 1986 – 1998    | RP82 / RP85 / RP86                 | RP82 / RP84 / RP86                   | '86-'92 / '93-'98             | RP72 / RP75 / RP76                 | RP72 / RP74 / RP76                   | '86-'92 / '93-'98             | RP114 / RP115                      | RP112 / RP115                        | '86-'92 / '93-'98             |
| Toyota | Tercel              | 1987 – 1990    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                               | RP72 / RP75 / RP76                 | RP72 / RP73 / RP76                   |                               |                                    |                                      |                               |
| Toyota | Tercel              | 1991 – 1998    | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   | '91-'94 / '95-'98             | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   | '91-'94 / '95-'98             |                                    |                                      | '91-'94 / '95-'98             |
| Toyota | Venza               | 2009 – present | n/a                                | RP82 / RP83 / RP86                   | extra labor on gas pedal      | n/a                                | RP72 / RP73 / RP76                   | extra labor on gas pedal      | n/a                                | RP112 / RP115                        | extra labor on gas pedal      |
| Toyota | Yaris               | 2007 – present | RP81 / RP85 / RP86                 | RP81 / RP83 / RP86                   |                               | RP71 / RP75 / RP76                 | RP71 / RP73 / RP76                   |                               | RP113 / RP115                      | RP111 / RP115                        |                               |

\* Note - It is recommended to remove the factory equipped metal slip-on cover before installing RAZO sport pedals on the following vehicle

- 2010- Ford Mustang GT
- 2010- Hyundai Genesis Coupe Tract
- 2007- Infiniti G35/37 Sport Pkg
- 2010- Kia Forte SX
- 2008- Mitsubishi Lancer Evolution
- 2007- Nissan Sentra SE-R

## GT Spec (bolt-on or drill)

## Grip Sport (bolt-on)

## LUXIS Type I (bolt-on or drill)

| Make   | Model               | Year           | GT Spec (bolt-on or drill)         |                                      |                               | Grip Sport (bolt-on)    |                            |                               | LUXIS Type I (bolt-on or drill)      |                                 |  |
|--------|---------------------|----------------|------------------------------------|--------------------------------------|-------------------------------|-------------------------|----------------------------|-------------------------------|--------------------------------------|---------------------------------|--|
|        |                     |                | Manual<br>(Accel+Brk&Clch/Ft Rest) | Automatic<br>(Accel+Brake/Foot Rest) | Remark                        | Manual (Accel+Brk&Clch) | Automatic<br>(Accel+Brake) | Remark                        | Automatic<br>(Accel+Brake/Foot Rest) | Remark                          |  |
| Toyota | 4Runner             | 1984 - 1989    |                                    |                                      |                               | RP25                    | RP23                       |                               |                                      |                                 |  |
| Toyota | 4Runner             | 1990 - 1995    |                                    |                                      |                               | RP25                    | RP23                       |                               |                                      |                                 |  |
| Toyota | 4Runner             | 1996 - 2002    |                                    |                                      |                               | RP25                    | RP23                       |                               |                                      |                                 |  |
| Toyota | 4Runner             | 2003 - present | n/a                                | RP101 / RP106                        | extra labor on gas pedal      | n/a                     | RP23                       | extra labor on gas pedal      | LS202 / LS204                        | extra labor on gas pedal        |  |
| Toyota | Avalon              | 1995 - 2004    |                                    |                                      | '95-'99 / '00-'04             |                         | RP24                       | '95-'99 / '00-'04             |                                      | '95-'99 / '00-'04               |  |
| Toyota | Camry               | 1992 - 1996    |                                    |                                      |                               |                         | RP24                       |                               |                                      |                                 |  |
| Toyota | Camry               | 1997 - 2001    |                                    |                                      |                               |                         | RP23                       |                               |                                      |                                 |  |
| Toyota | Camry               | 2002 - 2006    |                                    |                                      |                               |                         | RP23                       |                               |                                      |                                 |  |
| Toyota | Camry               | 2007 - present | n/a                                | RP103 / RP106                        | extra labor on gas pedal      | n/a                     | RP24                       | extra labor on gas pedal      | LS202 / LS204                        | accel. doesn't cover completely |  |
| Toyota | Celica              | 1986 - 1999    |                                    |                                      | '86-'89 / '90-'99             | RP25                    | RP24                       | '86-'89 / '90-'99             |                                      | '86-'89 / '90-'99               |  |
| Toyota | Celica              | 2000 - 2005    | RP104 / RP106                      | RP102 / RP106                        |                               | RP25                    | RP23                       |                               | LS202 / LS204                        |                                 |  |
| Toyota | Corolla GT-S (AE86) | 1984 - 1987    | RP104 / RP106                      | RP101 / RP106                        | SR5 model OK                  | RP25                    | RP22                       | SR5 model OK                  | LS201 / LS204                        |                                 |  |
| Toyota | Corolla             | 1988 - 1992    |                                    |                                      |                               | RP25                    | RP22                       |                               |                                      |                                 |  |
| Toyota | Corolla             | 1993 - 2008    |                                    |                                      | '93-'97 / '98-'02 / '03-'08   | RP25                    | RP22                       | '93-'97 / '98-'02 / '03-'08   |                                      | '93-'97 / '98-'02 / '03-'08     |  |
| Toyota | Corolla             | 2009 - present | RP105 / RP106                      | RP103 / RP106                        | extra labor on gas & MT brake | RP25                    | RP24                       | extra labor on gas & MT brake | LS201 / LS204                        | accel. doesn't cover completely |  |
| Toyota | Cressida            | 1985 - 1992    |                                    |                                      | '85-'88 / '89-'92             |                         | RP24                       | '85-'88 / '89-'92             |                                      | '85-'88 / '89-'92               |  |
| Toyota | Echo                | 2000 - 2005    |                                    |                                      |                               | RP25                    | RP22                       |                               |                                      |                                 |  |
| Toyota | Land Cruiser        | 1991 - 2007    |                                    |                                      | '91-'97 / '98-'07             | RP25                    | RP23                       | '91-'97 / '98-'07             |                                      | '91-'97 / '98-'07               |  |
| Toyota | Matrix              | 2003 - 2008    | RP104 / RP106                      | RP101 / RP106                        |                               | RP25                    | RP22                       |                               | LS201 / LS204                        |                                 |  |
| Toyota | Matrix              | 2009 - present | RP105 / RP106                      | RP103 / RP106                        | extra labor on gas & MT brake | RP25                    | RP24                       | extra labor on gas & MT brake | LS201 / LS204                        | accel. doesn't cover completely |  |
| Toyota | MR-2                | 1985 - 1996    | RP104 / RP106                      | RP101 / RP106                        | '85-'89 / '90-'96             | RP25                    | RP22                       | '85-'89 / '90-'96             | LS201 / LS204                        | '85-'89 / '90-'96               |  |
| Toyota | MR-2 Spyder         | 2000 - 2005    | RP104 / RP106                      | RP101 / RP106                        |                               | RP25                    | RP22                       |                               | LS201 / LS204                        |                                 |  |
| Toyota | Previa              | 1991 - 1997    |                                    |                                      |                               |                         | RP22                       |                               |                                      |                                 |  |
| Toyota | Prius               | 2001 - 2009    |                                    |                                      | '01-'03 / '04-'09             |                         | RP22                       | '01-'03 / '04-'09             |                                      | '01-'03 / '04-'09               |  |
| Toyota | RAV4                | 1996 - 2005    |                                    |                                      | '96-'00 / '01-'05             | RP25                    | RP23                       | '96-'00 / '01-'05             |                                      | '96-'00 / '01-'05               |  |
| Toyota | Supra               | 1986 - 1998    | RP105 / RP106                      | RP103 / RP106                        | '86-'92 / '93-'98             | RP25                    | RP24                       | '86-'92 / '93-'98             | LS202 / LS204                        | '86-'92 / '93-'98               |  |
| Toyota | Tercel              | 1987 - 1990    |                                    |                                      |                               | RP25                    | RP22                       |                               |                                      |                                 |  |
| Toyota | Tercel              | 1991 - 1998    |                                    |                                      | '91-'94 / '95-'98             | RP25                    | RP22                       | '91-'94 / '95-'98             |                                      | '91-'94 / '95-'98               |  |
| Toyota | Venza               | 2009 - present | n/a                                | RP103 / RP106                        | extra labor on gas pedal      | n/a                     | RP24                       | extra labor on gas pedal      | LS202 / LS204                        | accel. doesn't cover completely |  |
| Toyota | Yaris               | 2007 - present | RP104 / RP106                      | RP101 / RP106                        |                               | RP25                    | RP22                       |                               | LS201 / LS204                        |                                 |  |

\* Note - It is recommended to remove the factory equipped metal slip-on cover before installing RAZO sport pedals on the following vehicle

2010- Ford Mustang GT  
 2010- Hyundai Genesis Coupe Tract  
 2007- Infiniti G35/37 Sport Pkg  
 2010- Kia Forte SX  
 2008- Mitsubishi Lancer Evolution  
 2007- Nissan Sentra SE-R